





Assembly step 1: A box containing a wrench icon, a crossed-out power drill icon, and a warning triangle. To the right is a clock icon and the text "45'".

Assembly step 2: A box containing a block on a mat icon, a crossed-out block icon, and a warning triangle. To the right is a person icon and the text "1".




A




x 8

B




x 16

C




x 8

D




x 2

E






x 1

F







x 1



1





2





3





4







5




6



7



8



9

E



x 1

