




Diagram illustrating assembly instructions and warnings:


- Warning 1:** A triangle with an exclamation mark points to a box containing:
 - An icon of an L-shaped metal bracket.
 - An icon of a power drill with a slash through it, indicating that a power drill should not be used.
- Warning 2:** A triangle with an exclamation mark points to a box containing:
 - An icon of a rectangular block being placed on a textured surface.
 - An icon of a rectangular block with a slash through it, indicating that the block should not be placed on a hard surface.
- Time:** A clock icon is followed by the text **20'**, indicating an estimated assembly time of 20 minutes.
- Person:** An icon of a person is followed by the number **1**, indicating that one person is required for assembly.





A x 3








B




C x 4




1

B  x 1	C  x 4	D  x 4	E M8 x 73  x 4	F  x 1
--	--	--	---	--



2

A

x 3

