




Diagram illustrating assembly instructions and warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing:
  - A circular icon showing an L-shaped metal bracket.
  - An icon of a power drill with a diagonal line through it, indicating that a power drill should not be used.
- Warning 2:** A warning triangle with an exclamation mark is positioned above a box containing:
  - A circular icon showing a rectangular block being placed on a textured mat.
  - An icon of a rectangular block with a diagonal line through it, indicating that the block should not be placed directly on a hard surface.
- Time:** A clock icon is shown next to the text "40'", indicating an estimated assembly time of 40 minutes.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for assembly.




F




x 1

G




x 1

H




x 2

I




x 1

J




x 1

K




x 2

L



x 1


M



M4  
x  
20


x 16

N





x 16




!






1





2






3






4




5





6





7



8



9





!

