






Diagram illustrating assembly instructions and warnings:





- Warning 1:** A box containing a crossed-out power drill icon and a warning triangle with an exclamation mark.
- Warning 2:** A box containing a warning triangle with an exclamation mark, a clock icon, and the text "40'".
- Warning 3:** A box containing a warning triangle with an exclamation mark, a person icon, and the text "1".
- Warning 4:** A box containing a crossed-out icon of a block on a surface and a warning triangle with an exclamation mark.









!






1




2



3



4



C x 2

