








An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a drill should not be used.	A warning triangle containing an exclamation mark.	A circular clock face with tick marks around the perimeter.
	<p>30'</p>	
An icon showing a rectangular block on a surface with a hatched pattern, and another block with a screw being inserted into it, with a diagonal line through the scene, indicating that screws should not be used.	A warning triangle containing an exclamation mark.	A simple line drawing of a person.
	<p>1</p>	




A	B	C
		
x 1	x 2	x 1

1




x 2

2




x 4

3




x 4

4




x 10

5





x 10

6













x 1

!










1

A  x 1	C  x 1	1  M6 x 45 x 2	3  M6 x 80 x 4	4  x 6	5  x 6	6  x 1
--	--	---	---	--	--	--







2

<p>B</p>  <p>x 2</p>	<p>2</p>  <p>M6 x 60</p> <p>x 4</p>	<p>4</p>  <p>x 4</p>	<p>5</p>  <p>x 4</p>	<p>6</p>  <p>x 1</p>
---	--	---	---	---



3

<p>6</p>  <p>x 1</p>



!

