




Assembly instructions for the table, including tool requirements, time, and personnel.

Tools: A wrench is required (shown in a circle). A power drill is not required (shown with a diagonal line through it).

Warnings: A warning triangle with an exclamation mark is present.

Time: A clock icon indicates an estimated assembly time of 30 minutes.

Personnel: A person icon and the number 2 indicate that two people are required for assembly.



1

