




Diagram illustrating assembly instructions and safety warnings:


- Warning 1:** A triangle with an exclamation mark. Below it is a clock icon with the text **30'**, indicating a 30-minute assembly time.
- Warning 2:** A triangle with an exclamation mark. Below it is a person icon with the text **1**, indicating that one person is required for assembly.

The diagram also includes two rectangular boxes with rounded corners, each containing a circular inset and a crossed-out icon:

- The top box shows a circular inset with an L-shaped metal bracket and a crossed-out power drill icon.
- The bottom box shows a circular inset with a rectangular block on a textured surface and a crossed-out icon of a block with a screw being inserted into it.



x 1



x 1




x 2

1




x 1

2




x 2

3




x 4

4




x 4

5






x 10

6






x 10

1




2




3

1




x 1

4




x 4

5



x 4

6



x 4

