






TONSBERG







An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A simple clock face with tick marks around the perimeter.
<p>20'</p>		
An icon showing a rectangular block on a textured base inside a circle. To its right is the same block with a screw being inserted into its bottom, with a diagonal line through it, indicating this is not the correct assembly method.	A warning triangle containing an exclamation mark.	A simple stick figure representing a person.
<p>2</p>		


A



C x 4



A




x 1

C




x 4

D




x 8

E








x 8

F



x 1

1

<p>A</p>  <p>x 1</p>	<p>C</p>  <p>x 4</p>	<p>D</p>  <p>x 8</p>	<p>E</p>  <p>M8 x 35</p> <p>x 8</p>	<p>F</p>  <p>x 1</p>
---	---	---	--	---

