


# CERRETO








Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block being placed on a surface and another block being cut with a slash through it, indicating that the block should not be cut.
- Time:** A clock icon is shown next to the text "20'", indicating a 20-minute assembly time.
- Personnel:** An icon of a person is shown next to the number "2", indicating that two people are required for assembly.




D1




x 1

D2




x 1

D3




x 1

D4




x 1

D5




x 1

D6




x 1

D7




x 1

D8




x 1

1




x 5

2




x 3

3





x 1

4





x 1



1







2





3






4



5





6



7


1  
M6  
x  
60  
x 3

4  
x 1





8

D6  
x 1





9



!

