


# CERRETO








Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block being placed on a textured surface and another block being cut with a diagonal slash, indicating that the block should not be cut.
- Time:** A clock icon is positioned above the number **20'**, indicating a 20-minute assembly time.
- Personnel:** An icon of a person is positioned above the number **2**, indicating that two people are required for assembly.




E1




x 1

E2




x 1

E3




x 1

E4




x 1

E5




x 1

E6




x 1

E7




x 1

1




x 8

2





x 4

3





x 1





1







2





3






4



5




6




7

E6




x 1




8

E7



x 1





!

