

CERRETO









Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped metal bracket and a crossed-out power drill icon.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block on a textured surface and a crossed-out block with a double-headed arrow indicating a gap.
- Time:** A clock icon is positioned above the number **20'**.
- Personnel:** A person icon is positioned above the number **2**.




A1




x 1

A2




x 1

A3




x 1

A4




x 1

A5




x 1

A6




x 1

A7




x 1

1




x 2

2




x 4

3





x 2

4





x 1

1





2



3


2
M6
x
40
x 4

4
x 1




4

A5



x 1






5

1
M6
x
60
x 2


3
M6
x
25
x 2

4
x 1




6

A6
x 1




7

A7



x 1

A7



!

