


# CERRETO











Diagram illustrating assembly instructions and safety warnings:



- Warning 1:** A triangle with an exclamation mark. Below it, a box contains an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark. Below it, a box shows a rectangular block being placed on a surface with a hatched pattern, and another view shows the block being cut with a diagonal slash, indicating that the block should not be cut.
- Time:** A clock icon with the text "20'" below it, indicating a 20-minute assembly time.
- Personnel:** An icon of a person with the number "2" below it, indicating that two people are required for assembly.







1





2



3





4



5


2  
M6  
x  
60  
x 4

3  
x 1



6

B6  
x 1



!

