
















HOFN





 <p>A line drawing of a power drill with a diagonal slash through it, indicating that power tools should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A clock face icon.</p>
 <p>Two line drawings of a rectangular block. The left one is on a textured surface with a diagonal slash through it. The right one is being cut by a power saw with a diagonal slash through it, indicating that power saws should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	<p>10'</p>  <p>2</p>



A	B	C	D	E
				
x 1	x 1	x 1	x 1	x 4

1

B




x 1

C





x 1

E




x 4






2

A



x 1



3

