
















HOFN





 <p>A line drawing of a power drill with a diagonal slash through it, indicating that power tools should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A clock face showing approximately 10:10.</p>
 <p>Two icons: a screwdriver on a block of wood (circled) and a screwdriver on a block of wood with a diagonal slash through it, indicating that screwdrivers should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	<p>10'</p>  <p>2</p>



A	B	C	D	E
				
x 1	x 1	x 1	x 1	x 4

1

B




x1

C




x1

E



x4




2


A




x1



1a



1b



3

