











Diagram showing a warning symbol (triangle with exclamation mark) above a box containing an Allen key and a crossed-out power drill. To the right is a clock icon and the number 20'.






20'






Diagram showing a warning symbol (triangle with exclamation mark) above a box containing a block on a mat and a crossed-out block with a hammer. To the right is a person icon and the number 2.



2



1

<p>1</p>  <p>x 1</p>	<p>2</p>  <p>x 4</p>	<p>A</p>  <p>M8 x 20 x 16</p>	<p>B</p>  <p>x 16</p>	<p>C</p>  <p>x 1</p>
---	---	--	--	---

