


# BRACCIANO


















Diagram illustrating assembly instructions and warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped bracket and a crossed-out power drill, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block on a textured surface and a crossed-out block with a double-headed arrow, indicating that the block should not be placed on a textured surface.
- Time:** A clock icon with a circular arrow indicates a duration of 10 minutes.
- Personnel:** An icon of a person indicates that 1 person is required for this step.



A	B	C	1	2	3
			 M6 x 20		
x 1	x 4	x 1	x 16	x 16	x 1

1



2

