













An L-shaped metal bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A simple clock face with tick marks and two hands.
A rectangular block is shown on a mat with a hatched pattern. To its right is the same block with a screw being inserted into it, crossed out with a diagonal line.	A warning triangle containing an exclamation mark.	A simple stick figure representing a person.

40'








2



A	B	C	D	E
				
x 3	x 1	x 1	x 1	x 1





F	G	H	I	J
		 M6 x 19		
x 8	x 2	x 16	x 16	x 1

1

D	E	F	G	H	I	J
						
x 1	x 1	x 8	x 2	x 16	x 16	x 1



2



3

