







Diagram illustrating assembly instructions and warnings:





- Warning 1:** A box containing a crossed-out power drill icon and a warning triangle with an exclamation mark.
- Warning 2:** A box containing two icons: one showing a block on a mat and another showing a block with a crossed-out screw, and a warning triangle with an exclamation mark.
- Time:** A clock icon with the text "20'" below it.
- Person:** A person icon with the number "1" below it.







1





2



3



4



5

