








Diagram illustrating assembly instructions and warnings:





- Warning 1:** A warning triangle with an exclamation mark is shown above a box containing an Allen key and a power drill with a slash through it, indicating that a power drill should not be used.
- Warning 2:** A warning triangle with an exclamation mark is shown above a box containing a rectangular block on a textured surface and a block with a slash through it, indicating that the block should not be placed on a soft or uneven surface.
- Time:** A clock icon is shown next to the text "15'", indicating a 15-minute assembly time.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for assembly.



1



2



3

