








An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle with an exclamation mark inside.	A clock face showing 30 minutes.
An icon showing a rectangular block on a surface with a hatched pattern. To its right is the same block with a screw being inserted into it, crossed out with a diagonal line, indicating it should not be done.	A warning triangle with an exclamation mark inside.	A simple icon of a person.

30'




1








1






2



3



4





5

E
M6
x
15
x2






G
x2

I
x1



6

I
x1



7

