







An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon showing the time as approximately 1:50.
An icon showing a rectangular block on a mat with a diagonal line through it, and another rectangular block with a diagonal line through it, indicating that the block should not be placed on a mat or used in a certain way.	A warning triangle icon with an exclamation mark inside.	A simple icon of a person standing.
<p>15'</p>		<p>1</p>


<p><b>A</b></p>  <p><b>x 1</b></p>	<p><b>B</b></p>  <p><b>x 4</b></p>	<p><b>C</b></p>  <p><b>x 4</b></p>
---	---	---





- 4


- 3





- 1


- 2



<p><b>1</b></p>  <p><b>x 1</b></p>	<p><b>2</b></p>  <p><b>x 1</b></p>	<p><b>3</b></p>  <p><b>x 1</b></p>	<p><b>4</b></p>  <p><b>x 1</b></p>
---	---	--	---

1



2

