




WAPITI











Warning icons and symbols:

- Top box: A crossed-out power drill icon, indicating that power tools should not be used.
- Bottom box: A lightning bolt icon inside a circle, indicating an electrical hazard.
- Warning triangle: A triangle with an exclamation mark, indicating a general warning.
- Time icon: A clock face, indicating a 5-minute duration.
- Person icon: A simple human figure, indicating that 1 person is required for the task.




<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 3</p>	<p>C</p>  <p>x 1</p>
---	---	---

1



2



3

C



x1

