





# LOEN











An icon showing an L-shaped metal bracket inside a circle, next to a power drill with a diagonal line through it, indicating that a drill should not be used on this part.	A warning triangle icon with an exclamation mark inside.	A clock icon representing a time limit.
<p>10'</p>		
An icon showing a rectangular floor mat on a floor surface inside a circle, next to a screw being driven into the mat with a diagonal line through it, indicating that screws should not be used to secure the mat.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing the number of people required for the task.
<p>1</p>		

E



A	B	C	D	E
	 M2 x 10			
x 1	x 16	x 16	x 4	x 1

!



1

