



VARLEY








Assembly instructions for the table, including tool requirements, time, and personnel.

Tools: A circle containing a screwdriver and a wrench, and a crossed-out power drill icon, indicating that manual tools are required and power tools are not.








Warning: A triangle with an exclamation mark, indicating a warning or important instruction.



Time: A clock icon with the number **40'** below it, indicating that the assembly takes 40 minutes.

Personnel: A stick figure icon with the number **2** below it, indicating that two people are required for assembly.





1

A  x 1	B  x 2	C  x 2	1  x 8	2  x 8	3  x 8	4  x 1
--	--	--	--	---	--	--



2

D  x 2	5  x 4
--	--

