




A




B

A collection of safety and assembly icons. On the left, a rectangular box contains a crossed-out power drill icon. To its right is a warning triangle with an exclamation mark. Below the drill icon is a clock face with the number '30'' underneath it. At the bottom left, another rectangular box contains two icons: a cushion being placed on a mat and a crossed-out icon of a cushion being placed on a surface. To its right is another warning triangle with an exclamation mark. Below the second warning triangle is a stick figure icon with the number '1' underneath it.


A




D x 6




B x 9



C x 3




E x 3




A x 3

D




x 6

E




x 3

F






x 6

G






x 4



1 x 3






2





3






4






B



1




2






!



!



!

