


LUINO













Diagram illustrating assembly instructions and warnings:



- Warning 1:** A crossed-out power drill icon indicates that a power drill should not be used for assembly.
- Warning 2:** A crossed-out icon of a rectangular block being inserted into a hole indicates that the block should not be inserted in that manner.
- Time:** A clock icon with the number 5' below it indicates that the assembly time is 5 minutes.
- Person:** An icon of a person with the number 1 below it indicates that one person is required for assembly.




1





2



3



4



5

