



CIVITA








Assembly instructions for the table, including tool requirements, time, and person count.

Tools: Wrench and Power Drill (indicated as not needed).

Time: 15'

Person Count: 1


Warnings: Two warning symbols (exclamation marks in triangles) are present, one above the tool section and one above the person count section.



A	B	C	D
x 1	x 4	x 1	x 2

1

A



x1

B



x2

C





x1

D



x1



2

A



x1

B



x2

D



x1

