


Assembly instructions for the table, including tool requirements, time, and person count.

Tools: A circular icon contains a screwdriver. A power drill icon is crossed out with a diagonal line. A warning triangle with an exclamation mark is positioned to the right of the icons.

Time: A clock icon is shown above the text "15'".


Person Count: A person icon is shown above the text "1".



A x 1



B x 4



1

