





An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle with an exclamation mark inside.	A clock face showing approximately 12:30.
An icon showing a rectangular block on a surface with a hatched pattern. To its right is the same block with a screw being inserted into it, crossed out with a diagonal line.	A warning triangle with an exclamation mark inside.	A simple line drawing of a person.

30'




1







A




1



2



3



4

