












An L-shaped bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A clock face showing approximately 12:30.
A rectangular block is shown on a surface with a diagonal line through it. To its right is a similar block with a screw being inserted into it, also with a diagonal line through it, indicating it should not be done.	A warning triangle containing an exclamation mark.	A simple icon of a person.






30'

1



<b>A</b>  <b>x 1</b>	<b>B</b>  <b>x 2</b>	<b>C</b>  <b>x 1</b>	<b>D</b>  <b>x 1</b>
---	---	--	---





<b>E</b>  <b>x 1</b>	<b>F</b>  <b>x 1</b>	<b>G</b>  <b>x 5</b>	<b>H</b>  <b>x 2</b>
---	---	--	---

<b>I</b>  M6 x 20 <b>x 8</b>	<b>J</b>  M6 x 25 <b>x 6</b>	<b>K</b>  <b>x 8</b>	<b>L</b>  <b>x 6</b>	<b>M</b>  <b>x 1</b>
---	---	---	--	---




1






2





3



4



5



6

