





LOEN







An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a drill should not be used.	A warning triangle icon with an exclamation mark inside.	A clock icon showing approximately 10:10.
<p>20'</p>		
An icon showing a rectangular floor mat on a floor with a diagonal line through it, and a screw being driven into the mat, indicating that the mat should not be damaged.	A warning triangle icon with an exclamation mark inside.	A simple icon of a person standing.
<p>2</p>		

E



A	B	C	D	E
	 M2 x 10			
x 1	x 16	x 16	x 4	x 1

!



1

